

LOCOMOTIVE INSPECTION REPORT

DATE 11/11/2014 LOCATION Sano Springs OK  
 ROAD # 100 MODEL: SW900 FRONT: SHORT - LONG NOSE: LOW - HIGH  
 FRAME # \_\_\_\_\_ M.U.: (YES) - NO DYNAMIC: YES - (NO)  
 WHEELS: 1 27/8 2 27/8 3 23/8 4 17/8 5 \_\_\_\_\_ 6 \_\_\_\_\_  
 BOX TYPE: 1 F TIMKIN 2 F TIMKIN 3 F CONVERTED 4 F CONVERTED 5 \_\_\_\_\_ 6 \_\_\_\_\_  
 TRUCK TYPE: 1 AAR SW CYL; HI - LOW 2 AAR SW CYL: HI - LOW  
 RIGGING PIN TYPE: 1. CIASP 2 \_\_\_\_\_  
 TRACTION MOTOR: (IN) - OUT 1 \_\_\_\_\_ 2 \_\_\_\_\_ 3 \_\_\_\_\_ 4 \_\_\_\_\_ 5 \_\_\_\_\_ 6 \_\_\_\_\_  
 FUEL TANK SIZE: 60 gal COUPLER TYPE: E DRAFT GEAR TYPE: 485  
 PLOW TYPE: \_\_\_\_\_ PILOT TYPE: \_\_\_\_\_ GENERAL CONDITION: \_\_\_\_\_  
 BOTTOM END: \_\_\_\_\_  
 ENGINE TYPE: 8 cyl 56 FC S/N 56-A-79 E ENGINE BLOCK #: \_\_\_\_\_  
 CONDITION: ALLY - RUNNER

CHECK FOR DEFECT TAG: YES - NO  
 TURBO: \_\_\_\_\_ S/N: \_\_\_\_\_ PART #: \_\_\_\_\_ CONDITION: \_\_\_\_\_  
 DIFFUSOR CONDITION: \_\_\_\_\_  
 PAINT EXTERIOR: Good INTERIOR CAB: Good ENGINE ROOM: ALLY  
 AC CABINET: \_\_\_\_\_ FAN FUSES: YES - NO  
 AIR COMPRESSOR TYPE: WBD-LB-DAI CONDITION: Good  
 AIR BRAKE TYPE: 6 BL CONDITION: \_\_\_\_\_  
 MAIN GENERATOR TYPE: DISC CONDITION: 56A-34  
 AUX. GENERATOR TYPE: 20 KW CONDITION: \_\_\_\_\_  
 BLOWER WHEEL TYPE: \_\_\_\_\_ CONDITION: \_\_\_\_\_  
 FUEL PUMP: (YES) - NO OIL COOLER: (YES) - NO LOAD REG TYPE: Stand-up  
 DYN BRAKE/FAN: YES - (NO) 36 - 48  
 BELL: (YES) - NO HORN: (YES) - NO BATTERIES: (IN) - OUT - BROKEN  

COOLING FANS		# BLADES				TYPE
1. YES - NO	36" - 48"	6	8	9	10	CAST - FAB
2. YES - NO	36" - 48"	6	8	9	10	CAST - FAB
3. YES - NO	36" - 48"	6	8	9	10	CAST - FAB
4. YES - NO	36" - 48"	6	8	9	10	CAST - FAB

 RADIATORS: (IN) - OUT (SOLDERED) - MECHANICAL BOND  
 TOILET TYPE: \_\_\_\_\_ WATER COOLER TYPE: \_\_\_\_\_ FIRE EXT: \_\_\_\_\_  
 ELECTRICAL CABINET CONDITION: Good magnetic CONTACTORS

WIRE INSULATION TYPE: Exane CONDITION: Good  
 CAB CONDITION: FLOOR: WOOD GLASS: FRA Good SEATS: 3 Good  
 CONTROL STAND TYPE: CASH REGISTER CONDITION: Good RADIO EQUIP: \_\_\_\_\_  
 SPEED RECORDER TYPE: \_\_\_\_\_ ANGLE DRIVE TYPE: \_\_\_\_\_  
 CARBODY CONDITION / OVERALL CONDITION: Good

MISSING OR DAMAGED ITEMS: RACHET Style Handbrake  
BATTERY - Good 19 PLATE

Nice \* In Service Unit - Good

INSPECTOR: \_\_\_\_\_